

Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



WORK ORDER INFORMATION

Work Order Name: WO/80008KN0784/1
Work Order Type: Weatherization

Audit Name: 80008KN0784-Audit

CLIENT INFORMATION

Client Name:

Address:

Client ID: 80008KN0784

Alt. Client ID: Knox

<u>AGENCY INFORMATION</u>

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

House built in 1920

An EPA Certified Firm/Renovator is required.

Client Name:

Client ID: 80008KN0784
Alt. Client ID: Knox

Work Order (Bid Form)

Work Order Name: WO/80008KN0784/1 Report Run On: 5/8/2010 DOE Weatherization Assistant Version 8.6.0 Page 1 of 8

Measures

Measure 1	Attic Access Door			Componen	ts			Inspected
in: qu in:	ut in the ceiling an attic access a stalled as a complete unit. A do pality semigloss color to be chos sulation. No changes allowed. F eatherization Materials and Sou	or is inclu sen by ho Refer to A	sive of meowi ppend	foam seal, ner, caulk, R ix A- Standa	trim, pair -30 Batt	is nt(1st		
			-	Estimated			Actual	
# Material / Lai	bor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors	Attic Access Door	Each	1					
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	Labor	Each	1					
Other Detail								

		1	Measure	Sub Total:	74	S	ub Total:	
Field Notes:					- Paris			77

Measure 2 D			Componen	ts			Inspected	
Comment				·				
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
	Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.						· · · · · · · · · · · · · · · · · · ·	
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Fleid Notes:						WARLA	<u></u>	

Measure 3 DWH Tank Insulation					Inspected				
C	omment extend p	oressure relief pipe as ne	eded						
					Estimated	•		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.			[] <u>[</u>				
2	Labor	DHW Tank Insulation	Each	1					
C	ther Detail								10744444

	, ,			Measure	Sub Total:	***************************************]	Sub Total:	
ſ	Field Notes:					1 11111			

	Measure 4	Α	ttic Ins. F	₹-38				Compone	nts A1				Inspected
Comment •Includes labor cost. Contractor attic space showing depth of ins access. Install baffles as needer soffit and covering vent. Seal a insulating. Seal around chimner silicone or fire resistant foam. In access and weather strip with for Grade 1 Standards. Refer to Ap Materials and Southeast Field Grade 1 Standards.				f insuleded (al all l nney (n. Ins th foar	lation. Buto prever noles, ga with shee tall R-30 m tape. Cendix A-3	rild ins nt loose ps, an nt meta fiberg Contrac	ulation dame fill insulation penetration in and high the lass batt sector to insta	around on from ons in att emperat cured to	atteniic lure	tic tering before e tic	3		
.,								Estimate	d			Actual	
#	matoriar, Et	bor		ption / Comme		Units	Qty	Unit Cost	Total		Qty	Unit Cost	Total
1	Insulation			nsulation - Blow lass - R-38	wn	SqFt	1300		777				
2	Labor			nsulation <i>-</i> Blov lass - R-38	wn	SqFt	1300						
2	Other Detail												
Ĺ	74.												
											:		
						ı	Measur	Sub Total:				Sub Total:	
	Field Notes:									-	207.1.2		

		all Insulation		?,Wall	Inspected				
Con	Contra Contra installi interio up are	les labor cost. Contractor ractor must dense pack insunctor's responsibility to instang wall insulation. Contractor or exterior if needed while a around house and clean dix A- Standards for Weatl	ilation at a all wood cotor's resp installing siding off	3.5 pou or Styrc oonsibil g wall ii f after r	inds per squ ofoam plugs ity to repair valuation. Con neasure com	are foot in holes vall dan ontracto	after after nage or to clea Refer to	n	
					Estimated			Actual	
# M	laterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 In	nsulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1217		74			
2 La	abor	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1217		77			
Othe	er Detall								
<u> </u>									
				Measure	Sub Total:		s	ub Total:	
Fle	eld Notes:							L	

Measure 6 CO Monitor is Needed				Components					
Comment Refer to Field Gu	Attachment A- Standard uide.	s for Wea	theriz			outhea	st	Inspected	
				Estimate	ed		Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
 Health and Safety 	CO monitor	Each	1						
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.					J (
2 Labor	Labor	Each	1					******	
Other Detail					<u> </u>				
][
			loseur	e Sub Total:] []]	Sub Total:		
(Wall Comment A Certifie submit co	tice Lead Safe Weatheri s) ed Firm /Renovator is req opy of Lead Report and :	uired to a	dhere	Componer to EPA RR e, during, a	Prules 1	leed to		Inspected	
activity.				Estimate					
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total		Actual	~	
	EPA RRP Lead Rules	Each	1		, ota,	Qty	Unit Cost	Total	
	Labor	Each	4			[]{			
	Labor	Lacii	1						
Other Detail									
		M	easure	Sub Total:		S	ub Total:		
Field Notes:			17001						

Work Order Grand Total:	Grand Total:	_]
	 	j

Client Name:

Client ID: 80008KN0784

Alt. Client ID: Knox

Work Order (Bid Form)

Work Order Name: WO/80008KN0784/1

Report Run On: 5/8/2010

DOE Weatherization Assistant Version 8.6.0

Page 8 of 8